



restaurante na ilha do cabo

hotelaria e restauração hotels and restaurants

O restaurante tem uma localização privilegiada na ilha de Luanda. O conjunto edificado é composto por um paralelepípedo no qual estão pousados dois pequenos volumes. O corpo principal tem as suas fachadas claramente diferenciadas: a fachada voltada para a rua é totalmente cega enquanto a fachada que encara o mar é francamente aberta. A entrada é assinalada através de um volume balançado. Deste espaço exterior acede-se quer à sala de refeições climatizada quer à esplanada exterior. Na cobertura do edifício desenha-se uma área de lazer com apoio de bar.

This restaurant has a privileged location on the *Cabo* island in *Luanda*. The building development consists of a rectangular volume on which two smaller volumes are perched. The main structure has two clearly differentiated facades: the street side facade is windowless while the facade facing the sea is completely open. The entrance is formed by the space underneath one of the smaller volumes, which is balanced above. From this outdoor area both the air-conditioned dining room and the outdoor terrace are accessible. Built on the rooftop is a leisure area with a bar.

cliente client
Petrotec

local location
Luanda, Angola

projecto project
2008

área bruta gross floor area
685 m²

soapro estudos e projectos
arquitectura architecture
estruturas structures
inst. hidráulicas hydraulic eng.